

## 2026 Surplus List

1. Coats 50X-AH-1 Rim Clamp Tire Machine; (Purchased 2012); Pneumatic Engine; Good Body Condition; Machine Operates, but has an air leak from foot valves; Turn table slowly rotates even when pedal is not pressed. Trades
2. Squad Car 225; (2016); Chevrolet Tahoe PPV; Mileage 149,271; 5.3L V8; Rebuilt transmission 2/4/25; Engine starts; Condition of Tires and Body are OK; Drivable; Check engine light; Misfire; Rust on bottom fenders and rockers; Rear bumper damage on passenger side; Small dents and paint chips throughout body; Includes rear cargo area partition. Public Safety
3. BH-304 Batwing Rotary Cutter; (2003); Make – Woods, Model – 2120R-3/9309; Condition of Tires are Fair, Body is Well Used; Newer lift cylinder on wing, cutting height 2” to 14”, cutting width 122”, Tractor PTO RPM 540, Tractor HP 40-100, Input Universal Drive Cat 5 Heavy, Four blades, Tongue weight 1,500 lbs. Trades
4. M-306 Toro Grounds Master 4000D (Diesel); (2008); Model – M/N 30410; 2647 Hours; Engine – Kubota V2003T Diesel; Condition of Tires are Poor; Condition of Body is Well Used with cracks on hood; 11’ mow width; Approximate weight 2205 lbs. North Ops
5. M-320 Toro Z Master 5000 60” Propane; (2018); 755.5 Hours; Engine – 747cc Propane; Engine Starts; Condition of Tires and Body are Fair; Comes with two propane tanks; 60” cutting width. North Ops
6. M-321 Toro Z Master 5000 60” Propane; (2018); 296.1 Hours; Engine – 747cc Propane; Engine Starts; Condition of Tires and Body are Fair; Comes with two propane tanks; 60” cutting width; Missing battery and front castor wheel. 60” cutting width; Runs but down on power. North Ops
7. T-302 New Holland 445D Turbo 2WD; (2000); Model – KD5PW2 (445D / 2WD); 436.6 Hours; Engine – 3.1L (192 CI) Ford Turbo Diesel 60 HP; Condition of Tires is Poor; Condition of Body is Fair; Replaced radiator in 2022; Newer alternator; Engine oil leak; Hydraulic leak in rear; Control valve sticks/hard to operate. Trades
8. C-308 John Deere Gator XUV620i 4x4; (2010); 4367.7 Hours; Engine – Kawasaki FD620 .617L Gas; Engine does not start, but will crank; Battery good when parked; Condition of Tires is Poor; Condition of Body is Fair; Comes with cab. North Ops
9. C-306 John Deere Gator HPX 4x4; (2008); Model – Gator HPX 4x4; 1704 Hours; Engine – Kawasaki 617cc Gas; Engine starts; Condition of Tires are Good; Condition of Body is Fair; Electric dump bed; 4x4; Small melted spot in bed liner; Front passenger side wheel well has broken floor board. North Ops

10. Trailer 306; (2005); Make – Felling; Model – FT-12-2000 Deck Over; Mileage – N/A; Condition of Tires is Fair; Condition of Body is Fair; Not drivable; Rusted undercarriage; corroded frame; broken springs; will need to be trailered. North Ops
11. T#322 2010 Ford F-450 4x4; Mileage 68,679; Engine – 6.8L V10 Gas, Engine Starts; Condition of Tires is Fair; Condition of Body is Fair; Drivable; Transmission pan leaks, ABS light on; Transmission clicking noise; 8-foot dump body; Includes Western plow and Salt Dog spreader w/ spinner. North Ops
12. T#324 2012 Ford F-350 4x4; Mileage 78,677; Engine – 6.2L V8 Gas; Does not start; Condition of Tires and Body is Fair, Not Drivable; Battery dead, Rear brakes seized, Electrical issues; Includes factory bed (not attached); Western plow. North Ops
13. T#326 2014 Ford F-450 4x4; Mileage 52,230; Engine – 6.8L V10 Gas; Starts; Condition of Tires is Fair/Poor; Condition of Body is Fair; Drivable; Exhaust leak; Hydraulic tank seeping; Includes Western plow and Salt Dog spreader/spinner. North Ops
14. T#104 2010 Ford F-350; Mileage – Still in use; Engine – 6.4L Power Stroke V8 Turbo Diesel; Starts; Condition of Tires and Body are Good; Drivable; TPMS Light on; Intermittent Check Engine Light. Trades.
15. T#416 2006 International 7400 SFA 6x4; Mileage – Still in use; Engine HT570 310 HP/2200 RPM GOV SPD; Engine starts. Condition of Tires and Body are Fair/Good; Drivable; 6x4 Dump Body; Air Brakes; Trailer Air Brake gladhands; Electric Trailer Brake connection; Surface Rust throughout frame & dump body; Fair to good condition for age. South Ops
16. T#425 2012 Ford F-450; Mileage 54,865; Engine – 6.8L V10 Gas; Starts; Condition of Tires is Fair/Good; Condition of Body is Poor; Drivable; Dump body severely rusted; Brake noise when stopping; Includes Western Plow and Tailgate-mounted spreader/spinner. South Ops
17. T#428 2014 Ford F-450; Mileage 41,513; Engine – 6.8L V10 Gas; Does not start; Condition of Tires and Body are Fair/Good; Not Drivable; Brake and power steering issues; does not start (unknown reason); Tailgate upper release handle broken; Tailgate won't lay flat; Includes Western Plow and Tailgate-mounted spreader/spinner. South Ops
18. T#67 2012 Ford F-550; Mileage – Still in Use; 6.7L Power Stroke V8 Turbo Diesel; Starts; Condition of Tires are Good; Condition of Body is Fair; Drivable. Natural Resources.
19. M-41 Schulte XH1500 Rotary Mower; (2004); Condition of Tires are Fair; Condition of Body is Good; Drivable; Precision hitch; Newer main PTO shaft; One wing gearbox broken; Foam filled tires. Natural Resources
20. Plow 1950-1957 Ford Dearborn 10-158; Drivable; Condition of Body is Fair; 3-point plow; 2 bottom 12"; Serial #3600. North Ops

21. Squad Car 224; (2015); Chevrolet Tahoe PPV; Mileage 121,000; 5.3L V8; Engine starts; Condition of Tires and Body are OK; Drivable. Public Safety
22. Squad Car 227; (2017); Chevrolet Tahoe PPV; Mileage 182,643; 5.3L V8; Engine starts; Condition of Tires and Body are OK; Drivable. Public Safety
23. Antique Wood Two-Piece Cupboard; Armstrong's Linoleum; Top Piece 44"x15.5"x41"; Bottom Piece 46"x20"x45.5"; Poor Condition; Top piece is loose and is mildewed. North Ops
24. Two-Unit Solid Black Cherry Wood Dressers with Mirror; Virginia Galleries – The Henkel Harris Co; Long Dresser 66"x21.5"x35"; Tall Dresser 36"x20.75"x56"; Mirror 52.5"x1.75"x34.5"; Good condition; Dressers have 8 drawers each; One dresser drawer will not pull out fully; No mounting bracket for mirror. North Ops
25. Brass Plated Trunk; Sarreid Ltd (Crafted in Spain); 34"x19.5"x16"; Fair condition; Rear left foot doesn't tighten all the way; Brass is tarnished. North Ops
26. Large Antique Wood Wardrobe on Wheels; Manufacturer – Unknown; 42"x20"x85"; Fair condition; Wood trim damaged and missing; Packing stickers on furniture. North Ops